





CASE STUDY

Auto Manufacturing Site Astonished at Longevity of Mats



CHALLENGE

An auto manufacturing operation in Brampton, Ontario, Canada, was looking to increase safety on the floor of their plant. They had tried three different types of competitor mats and were frustrated with them—they ripped, broke down and they didn't significantly help with fatigue and comfort standing all day.

SOLUTION

They installed a Safe-Flex Floor System in a few areas to test them in comparison to the other mats. A month later they ripped out all the old mats in the plant and replaced them with Safe-Flex.

- Seven years later, the mats are still going strong.
- Workers continue to be thrilled with how much better they feel.
- There are areas in the plant where the operators drag parts across the tile and cause damage over time. Instead of ripping out and replacing entire areas, they remove the damaged tiles and replace with new ones, keeping maintenance cost effective.
- Old mats had to be taped down, but Safe-Flex mats do not.
- Old mats would develop bacteria and mold on the underside, these do not.
- Power cords are easily run under the tiles, removing tripping hazards.

“Simply put, ‘Best Matting Ever’ – while the initial cost is more, the longevity of the product is compared to nothing.”